Fire Assessment 2021

05 2021

12

10

12th May 2021

St Annes Court Willenhall WV13 2LY

12th May 2021



1 Introduction	5
1.1 Scope and Purpose	5
1.2 Legislation	5
1.3 Limitations and Exclusions	6
2 Record of Assessments	7
3 Property Overview	8
4 Occupancy Summary	10
5 Assessors summary of findings	11
6 Risk assessment grading	12
7 Findings and action plans – High Priority	13
8 Findings and action plans – Medium Priority	15
9 Findings and action plans – low priority and recommendations	16
10 Audit information	17
11 Life safety issues	17
12 Disability issues	18
11 Ignition sources	20
14 Electrical safety	21
14.2 Solar PV Panels	22
15 Security and arson controls	23
16 Fuel sources	23
17 COSHH and hazardous materials	23
18 Compartmentation	23
19 Door sampling – Front doors to flats	23
20 Means of escape – Internal	23
21 Means of escape – External	23
22 Fire fighting equipment	23
23 Fixed fire fighting installations	23
24 Smoke and ventilation systems	23
25 Fire evacuation lift and fire fighting shafts	23
26 Fire warning systems	23
27 Management of fire safety	23
28 Statutory training	
29 Evacuation Procedures	23
30 Emergency plan, threat procedure and fire fighting plan	
31 Photographic references	23

1.1 Scope and Purpose

- 1.1.1 A surveyor for whg has identified the significant findings and made recommendations and / or action plans in order to assist the Responsible Person in meeting their obligations under the Regulatory Reform (Fire Safety) Order 2005 (RRFSO) to the extent of responsibility for premises or parts of premises falling under its control. As this is a high rise block it falls under category 1 and a fire risk assessment on this block will be completed once every year.
- 1.1.2 This Fire Risk Assessment has been prepared and presented by surveyor Gary Reid which was reviewed on the 12th May 2021
- 1.1.3 The sole purpose of this report is to provide an assessment of the risk to life from fire, and to assist what in reducing the risk of fire to which the property may be exposed.

1.2 Legislation

- 1.2.1 The applicable legislation is the Regulatory Reform (Fire Safety) Order 2005. The RRFSO essentially replaces or amends all previous fire regulations and laws, for all buildings, other than those where the Health and Safety Executive (HSE) or the local authority is the enforcing authority.
- 1.2.2 The aim of the RRFSO is to consolidate the general fire safety precautions of various parts of legislation. The legislation places the responsibility for enforcing fire precautions within buildings on the local Fire Authorities. The responsibility for enforcement is retained by the Health & Safety Executive.
- 1.2.3 A risk-based approach is required under the RRFSO, in contrast to the prescriptive process previously imposed. The RRFSO requires that the 'Responsible Person' should undertake a fire safety risk assessment, such that it can be demonstrated that the fire safety precautions are adequate and maintained to reduce the exposure of 'relevant persons', see article 8 below:

"the responsible person must – (a) take such general fire precautions as will ensure so far as is reasonably practical the safety of its employees and (b) in relation to relevant persons who are not in their employ as may reasonably be required to ensure the premises are safe"

1.2.4 The Responsible Person can be defined as the owner, occupier, employer or person(s) in control of the building, whilst the relevant persons are described in the RRFSO as: -

'Any person who is or may be lawfully on the premises, and also any person in the immediate vicinity of the premises who is at risk from a fire in the premises', other than fire-fighters at the time of a fire'.

- 1.2.5 Under the RRFSO, it is required that the following information is stored and available for inspection onsite or be available:
 - The Fire Risk Assessment
 - Where actions are required, proof of completion
 - Record books detailing the preventative and proactive measures and any arrangements associated with fire safety; planning, organisation, control, monitoring, reviewetc.
 - Staff training
 - Previous Fire Events
 - Dates of Fire Risk Assessment and reviews
 - Copies of equipment test certificates

1.3 Limitations and Exclusions

- 1.3.2 The information and advice detailed within this report has been compiled following the principles of Publicly Available Specification; PAS79 and is considered to present a suitable level of fire safety taking in account the complexity of the building, proposed occupancy levels and local conditions. This report should be fully understood by the Responsible Person and the findings actions highlighted to be addressed within the timescales identified.
- 1.3.3 Unless explicitly stated this report does not include detailed evaluation of any fire protection equipment in terms of its adequacy or reliability, nor has the integrity of fire compartmentation been verified.
- 1.3.4 It is not considered practical for many older buildings to achieve full compliance with the current Building Standards due to their age and structural form. Consequently, the actions identified and recommended within this report should not be interpreted as a means of achieving compliance, but as a method of reducing risk and enhancing Life Safety and property protection.
- 1.3.5 The assessment relies on information obtained by the assessor by whg from their associated maintenance records prior of to the site visit.
- 1.3.6 This fire risk assessment covers the conditions of the property on the day of the inspection and from additional appropriate sources provided to the assessor by whg however does not necessarily apply to changes in conditions made after that date.
- 1.3.7 It is the whg's' responsibility to keep the fire risk assessment up to date; especially through any significant changes that may have taken place at the property.
- 1.3.8 It is considered reasonable to assume that any works identified will be in line with the recommendations of this report and be carried out with appropriate materials and in a competent manner.

1.4 Audit and Publication process

- 1.4.1 Following the preparation of this document a qualitative audit is undertaken prior to its publication. We endeavour to achieve this within 30 days of the fire risk assessment date.
- 1.4.2 As part of this audit process the remedial action target date will be inserted according to priority.
- 1.4.3 A compliance check will be undertaken following 91 days of published date.

Date of Assessment	Reason for Assessment	Comments	Name of Assessor
12.05.2021	FRA review and renewal	Re assessment.	Gary Reid
Date Published 19.05.2021			
Review Date 12.05.2022			

Brief Description of Property & Construction	Each floor 1- St Annes Ct i was refurbish consisting of and individu heating syste powered bo The front (ea The building	10 consists of 4 flats a system built consists of 4 flats a system built consided both externally Rockwool slab insurant flat doors were removed the flats a single escaphas a single escaption.	rpose built block of flats, built in 1960s, the ground floor consists of 2 occurstruction with concrete walls and a and the common parts internally. Ulation with a silicone render finish the placed into existing frames. The batter storage being located in the action plant room. Seed balconies were removed and the stairwell with one final exit to the	external brickwork skin. In This included an external brickwork skin. In This included an externation all elevations. Internall block was also upgraded djacent block St Giles Ct enclosed by a PVCu win front (east) elevation.	n 2015 the block al thermal wrap y all communal to a communal to and the gas dow façade.
No of Floors	10	No of Stair cases	1	Approximate Floor Footprint Area (sq. m)	340m²
No of Basement levels	0	Location(s) and Use(s) of stairs	1 centrally located Internal staircase accessing all floors from ground level, with final exit to front (east) elevation. Stairs located central at the front of the block.	Occupancy	Residential.
Area covered by this Assessment	the block. This is a Fire Risk Assessment (FRA) does not identify individual persons at risk It reviews current fire prevention methods, housekeeping and identifies how what can reduce or eliminate the risk of fire. The assessment has been carried out following the Local Government Group guidance "Fire Safety in purpose-build block of Flats" (type 2 survey) it does not include destructive testing beyond the front door of the flat. The areas covered within this assessment are communal areas, community room, bin storage rooms, Plant room, service cupboards, dry risers, flat entrance doors, escape routes and the external perimeters around the building.				

The property is a hi-rise residential block. Fire warning systems are provided within the block and they are connected to Auto-dial systems for an early warning in the event of a fire. Localised automatic detection may be provided within each residence, but this is not interconnected between individual flats.
Physical separation between individual flats and communal areas reduces the potential for fire spread and imperforate structural protection to the stairwell maintains the availability of the circulation stair for evacuation and firefighting access. In the event of fire occurring, a 'stay safe' policy has been promoted by whg where residents will not evacuate unless directly affected by fire or smoke; or instructed to do so.
The risk to tenants within their home is not considered by this assessment; however, this may be individually addressed by community fire safety, care workers or via SPIN (Supporting People In Need) where appropriate.
Physical compartmentation is present between the circulation stairwell, the residential flats and the communal areas. Fire doors located across the communal landings and at the access points to the stairwell assist in preventing lateral and vertical fire spread. Fire stopping works have been installed to further prevent the passage of fire and smoke. This has included the installation of intumescent seals to the stairwell and landing doors, the sealing up of vertical shafts and the infill of gaps within cupboards and inset electrical meter cupboards. At present there is a major refurb of the refuse area and this has incorporated all hoppers to the chutes being blanked off whilst works are in process.
The likelihood of accidental fire occurring within the communal areas is very low due to the lack of potential ignition sources and fuels. The electrical distribution cupboards contain a viable ignition source, but this is considered to be a low risk. The potential for fire is greater within the residential properties where uncontrolled activities are permitted, i.e. cooking and smoking. If an accidental fire occurs within a residence, the alarm will have to be raised locally and the Fire and Rescue Service contacted. Fire spread will be restricted from entering the communal areas provided the flat entrance door is kept closed. The fire will continue to develop within the room of origin, involving the available combustible fuels until positive intervention by the attending Fire and Rescue Service.

	Person responsible for	Designation			С	ontact Details		
	Fire Safety			Office	Mobile	Email	Other	
	Paul Dockerill	Director of energy and programme management		0300 555 6666		Paul.Dockerill@whgrp.co.uk		
	Person responsible for				C	ontact Details		
	Fire Safety Maintenance Programme	Designation		Office	Mobile	Email	Other	
	Nigel Harris	Director of Home Main	ntenance Services	0300 555 6666	07831387364	Nigel.Harris@whgrp.co.uk		
	Person providing	Dosig	nation		C	ontact Details		
	assessment information	Desig	nanon	Office	Mobile	Email	Other	
	Gary Reid	Building Surveyor		0300 555 6666	07831624662	Gary.reid@whgrp.co.uk		
Ī						<u> </u>		
	Name of Owner			Persons Present - Max Nos. (approx.) Daytime / Silent Hours				
		Location	Activity	Employees	Young Persons	Members of Public	Tenants	
	Whg 100 Hatherton Street Walsall WS1 1AB	St Annes Court Rose Hill Willenhall WV13 2LY	Residential block of 43 flats. Communal areas are a transit space for tenants and Visitors.	≥5	Unknown	≥5	≥43	
			1 1011 0101					
Ì	Davage at Bist				Reason	and Numbers		
	Persons at Risk	Location	Activity	Sleeping	Disability	Remote Location	Other	

Risk Category	Summary of provision	Qualifying comments
Risk to Life	Risk to life is assessed as LOW .	No significant issues identified within the communal areas.
Risk to Firefighters	Risk to life is assessed as LOW .	No significant issues identified within the communal areas.
Risk to Property	Risk to property is assessed as MEDIUM .	Accumulations of salvage within the salvage room present a fire risk to the building and communal heating distribution pipework.
Risk of Fire	Risk of accidental fire is assessed as MEDIUM .	The potential for fire is low within the communal areas due to the lack of potential possible ignition sources.
Risk of Fire Spread	Risk of fire spread assessed as LOW TO MEDIUM .	The door bin store doors and frame to property ** raises the risk of fire spread into the communal area
Residual Risks	The residual risks found are accumulations of salvage and rubbish within the salvage rooms	This poses a risk to the building and communal heating infrastructure
Overall Summary	report.	MEDIUM. the grading have been listed for action within Sections 7-9 of this or further reduce the overall grading to MEDIUM.
Additional Recommendations		
Assessment Review Period	This block is identified as a category 1; a fire risk assessment will be completed once every 12 months.	Any changes e.g. Use, Tenant profile, structural alterations or other change may affect the outcomes of this assessment may require it to be reviewed immediately. All new findings must be actioned, and the FRA updated accordingly.

The priority reflects the most significant finding within the category. Other, less urgent issues may also have been identified and should be addressed.	PRIORITY
Major Improvement required within a short timescale. Signifies risk to life or property or failure to observe statutory requirements.	HIGH (7 Days)
Minor Improvement required within short to medium term timescale. Signifies minor infringement or poor process.	MEDIUM (45 Days)
Minor improvement recommended. Actions are not necessarily statutorily required but would improve the culture and effect of the fire safety strategy. No fixed timescale but should be considered medium to long term.	LOW (90 Days)
Improvement or refurbishment works to enhance and improve current fire safety measures.	PROGRAMME (90 day to assess and formulate into future programme)
The information required in this section does not apply to this particular property.	NOT APPLICABLE

Service Areas.

- PT- Projects Team.NC Neighbourhood Contracts.
- NIO Neighbourhood Impact Officers.
- ELE Electrical team

PMO – Programme Management Office
Findings and action plans – High Priority

Report and Photo Reference	Significant findings	Urgent Action Required	Target Date for Remedial Work	Corrective Action Completed	Service area
7.1.1	General; Unable to locate certification for fire alarm servicing and maintenance	Please provide in date certification			NC (Donna Brown) Neighbourhood contracts
7.1.2	General; Unable to locate certification for emergency lighting, satisfactory cert and Lightning protection	Please provide in date certification			ELE Electrical team
7.1.3	General; Unable to locate certification for the dry riser	Please provide in date certification			NC (Donna Brown) Neighbourhood contracts

7.1.4	General; Unable to locate certification for the door entry system	Please provide in date certification		NC (Donna Brown) Neighbourhood contracts
7.1.5	General; Unable to locate certification for the retro cladding	Please provide the retro fit Rockwool EWI certification.		Development team

Report and Photo Reference	Significant findings	Prompt Action Required	Target Date for Remedial Work	Corrective Action Completed	Service area
8.1.1 Photo ref. 01	General; No assembly point on the action plan	Provide a designated assembly point on the action plan			NIO
8.1.2 Photo ref. 02	General; Contractors items in electrical cupboard	Remove contractors' items from the electrical cupboard floor 6			PMO
8.1.3 Photo ref. 03	General; Rubbish in the protected stairwell	Remove all items and investigate to whom is leaving items			NIO/TS
8.1.4 Photo ref.04	General; Hole to the electrical cupboard	Seal hole with an intumescent sealant to the wall			PT

ſ						
	Report and Photo Reference	Significant findings	Long Term Action Required	Target Date for Remedial Work	Corrective Action Completed	Service area
		General; Vulnerable customers in the block	Customers to be contacted to arrange PEEPS – personal emergency evacuation plan – contact surveyor for more information.			TS
	Photo ref. 05	General; Block is undergoing extensive refurbishment works to the refuse room and all chute hoppers are currently sealed and cupboards X1 to each communal floor has been isolated	Once work is complete all compartmentation to these areas must be inspected for compliance			PMO

The following information was gathered during the assessment process and is subject to change due to changes in occupancy, use, structural alteration etc. All subject areas should be re-visited during any re-assessment process to identify a new overall assessment outcome.

11 Life safety issues

11.1	Areas to Assess	Yes	No	Assessor Comments
11.1.1	Are there persons at significant risk within the property	✓		The profile of the customers within St Annes Ct is mixed there may be residents that will have mobility and sensory impairments. St Annes Ct is a residential building and not staffed, therefore customers must ensure they take necessary fire precautions within their flat and regularly familiarise themselves with whg's stay safe policy and fire safety guidance.
	Staff work out of hours or are lone working	✓		There are many lone visits within the organisation along with
11.1.2				the out of hour's team attending when needed.
	There are existing risks to Firefighters		✓	No significant risks to firefighters in this block, the block is at low risk of
11.1.3				fire.
	Visitors and Contractors are controlled	✓		Contractors are monitored by the relevant contracts
11.1.4				manager/officers where applicable. whg have no control over non
				contracted whg services or customers visitors to the block.

12.1	Areas to Assess	Yes	No	Assessor Comments
12.1.1	There are persons who require additional assistance in emergency situations within the property	√		The profile of the customers within St Annes Ct is mixed there may be residents that will have mobility and sensory impairments. St Annes Ct is a residential building and not staffed, therefore customers must ensure they take necessary fire precautions within their flat and regularly familiarise themselves with whg's stay safe policy and fire safety guidance.
12.1.2	Fire evacuation procedures consider disabled personnel		<	The profile of the customers within St Annes Ct is mixed there may be residents that will have mobility and sensory impairments. St Annes Ct is a residential building and not staffed, therefore customers must ensure they take necessary fire precautions within their flat and regularly familiarise themselves with whg's stay safe policy and fire safety guidance.
12.1.3	'Disability specific' signs are in place e.g. to indicate wheelchair routes to refuge areas etc		\	There are no refuge areas or Disability specific signage within St Annes Ct.
12.1.4	The need to support the evacuation of visually impaired persons has been considered and procedures established		✓	The profile of the customers within St Annes Ct is mixed there may be residents that will have mobility and sensory impairments. St Annes Ct is a residential building and not staffed, therefore customers must ensure they take necessary fire precautions within their flat and regularly familiarise themselves with whg's stay safe policy and fire safety guidance.
12.1.5	Hearing impaired occupants can readily identify the fire warning system actuation.		✓	As 12.1.4

People with Cognitive disorders have been	✓	As 12.1.4
12.1.6 considered, procedures established		
and people informed		

13.1	Areas to Assess	Yes	No	Assessor Comments
13.1.1	Significant potential Ignition sources are present		✓	
13.1.2	There are significant potential ignition processes in use		✓	
13.1.3	Process control measures are in place			
13.1.4	Gas-powered appliances are in use			The communal heating system is gas fired however the boiler is located in a separate plant room in St Giles Ct the adjacent block. Customers are also advised not to use bottled gas appliances within this block.
13.1.5	Space heating method is appropriate	✓		There are no heating appliances within the common parts of St Annes Ct
13.1.6	No Smoking signs are visible	√		On each floor and stair landing
13.1.7	Suitable provisions are made for smokers	√		Customers may smoke within their own flat but smoking is not allowed in the common parts of St Annes Ct.
13.1.8	There are signs of breaches of policy		√	
13.1.9	There is lightning or earthing control	√		The block has lightning protection.
13.1.10	It is tested and records maintained in accordance with BS 6651 BS7430		√	Action raised
13.1.11	Contractors are regularly monitored during Work	✓	✓	Contractors are monitored by the relevant contracts manager/officers where applicable. whg have no control over non contracted whg services or customers visitors to the block.
13.1.12	Contractors work methods are pre- approved (hot work permits, SSOW)			All whg contractors are to provide risk and method statements prior to works. No hot works are allowed in St Annes Ct by whg contractors

	Communal electrical equipment is appropriate	√		
14.1.1	to the use of the property and is not misused			
	Communal electrical equipment is	✓		Where applicable (lighting/main entrance doors)
14.1.2	operated by time switches			
	Communal portable electrical equipment	✓		
14.1.3	has been inspected on a regular basis and			
	results			
	recorded			
	There is evidence of overloading of electrical		✓	
14.1.4	sockets or extensive use of cable drums,			
	multi way extensions or transformer plugs in			
	communal areas.			
	The fixed electrical installation in the		✓	
14.1.5	communal area is checked regularly in			Action raised
	accordance with current IEE Regulations			
	Records of testing are maintained and		✓	As above
14.1.6	available			
	Defects noted during testing have been		✓	As above
14.1.7	rectified			
	Cupboards containing Main Electrical		✓	Action raised
14.1.8	Distribution boards are free from combustible			
	storage or the storage is so positioned as to			
	pose a low risk of fire			

14.2 Solar PV Panels

14.2	Areas to Assess	Yes	No	Assessor Comments
14.2.1	Does the block have solar pv panels ?		√	
14.2.2	Compliance with fire safety legislation Has a suitable and sufficient fire risk assessment been undertaken in compliance with the Regulatory Reform (Fire Safety) Order 2005 (or equivalent legislation in Scotland and Northern Ireland) or been reviewed following the installation of PV panels?			
14.2.3	Fire safety management Are windblown litter and leaves not allowed to accumulate, especially around or beneath PV panels?			
14.2.4	Is the possibility of deliberate fire rising from outside the building by intruders or from within by staff addressed?			
14.2.5	Is automatic smoke detection inside a building, especially those that are normally unoccupied, in which electrical control equipment for PV panels is located?			
14.2.6	Are a suitable number of appropriate portable fire extinguishers available adjacent to the control and switchgear and immediately accessible in the case of a fire?			
14.2.7	Is care taken that obstructions and stored materials do not reduce the level of ventilation provided for the inverters?			
14.2.8	Is the installation serviced and maintained in accordance with the installer's instructions?			

15.1	Areas to Assess	Yes	No	Assessor Comments
15.1.1	The property has experienced fires or other incidents in the previous 12 months		√	There are no recorded fires at this block within the 12 months prior to this assessment
15.1.2	All incidents have been investigated and recorded	√		False alarms are recorded and monitored by BAYDALE.
15.1.3	Combustible materials are stored in close proximity to the building		✓	
15.1.4	There is a regular, routine check of Fire Safety measures undertaken	✓		This block is subject to a daily inspection by the Neighbourhood Impact Officers (NIO's) who have been trained on basic fire safety measures and more specific training on basic fire door inspections.
15.1.5	Safety Check findings are recorded and identified problems corrected	√		Issues are recorded and raised by the NIO's for whg's repairs teams
15.1.6	Access to the site and / or property is effectively controlled	√		St Annes Ct benefits from a secure door entry system controlled by the customers.
15.1.7	There is CCTV or physical monitoring	✓		St Annes Ct has the benefit of CCTV which is monitored 24hrs by whg's own CCTV security team.
15.1.8	Tapes/discs are kept for a minimum of 30 days (CCTV protocol)	√		
15.1.9	Gates / perimeter access points are suitably protected to prevent unauthorised access but permit egress	√		

16.1	Areas to Assess	Yes	No	Assessor Comments
16.1.1	The standard of general housekeeping is adequate		√	Rubbish in the protected area, action raised
16.1.2	Fuel sources and ignition sources are kept Apart	√		
16.1.3	There are significant potential sources of Fuel		✓	
16.1.4	There are accumulations of unnecessary combustible materials or waste		✓	The storage of items with bi stores are also allowed in this area, this should be removed and a suitable location away from the building identified. (failure to address this could result in significant impact on the heating system to St Annes Ct due to the location of the heating distribution pipework)
16.1.5	Soft furnishings have compliant upholstery Finishes	√		There are no soft furnishings within the common parts of St Annes Ct.
16.1.6	There are sources of Oxygen or supporters of combustion, apart from ambient air	✓		Given the age profile of the customers within St Annes Ct some of the customers may be on medical oxygen, the local Fire and Rescue Service will be notified of such addresses by the oxygen supplier
16.1.7	There are potential sources of dust ignition	✓		

17.1	Areas to Assess	Yes	No	Assessor Comments
17.1.1	Hazardous chemicals are present		√	
17.1.2	Suitable arrangements are in place to manage the elimination or reduction of risks from hazardous substances	✓		whg manage any asbestos within the building in accordance with the Control of Asbestos Regulations 2012 Regulation 4. (CAR 2012)
17.1.3	Hazardous chemicals are effectively controlled during use and in storage			
17.1.4	Waste materials are adequately controlled	√		whg manage any asbestos within the building in accordance with the Control of Asbestos Regulations 2012 Regulation 4. (CAR 2012)
17.1.5	Suitable and appropriate signage is present	√		whg manage any asbestos within the building in accordance with the Control of Asbestos Regulations 2012 Regulation 4. (CAR 2012)
17.1.6	Material safety data sheets are available	√		Material data sheets are available for all products used by whg and their contractors.

18.1	Areas to Assess	Yes	No	Assessor Comments
18.1.1	There is a risk of hidden Fire Spread within the structure		✓	
18.1.2	There is a risk of vertical or lateral spread within the property e.g. between occupancies or via common areas	~		Being addressed with the current refurbishment works.
18.1.3	The basement (where present) is separated from the ground storey by 30 minutes FR construction (minimum)			
18.1.4	The risk of Fire Spread is effectively controlled	✓		
18.1.5	The property is sub divided into fire compartments	✓		
18.1.6	There are unprotected openings, gaps or holes in compartment walls	√		As Per 18.1.2
18.1.7	Wall and ceiling linings routes add to the risk of flame spread	√		As Per 18.1.2
18.1.8	The building has cladding on its external faces	√		St Annes Ct received an External Wall Cladding system in 2015 comprising of Rock-wool slab insulation with a silicone render finish.
18.1.9	As built cladding specifications and completion certification are available		√	Action raised

The cladding meets Building Regulations	√	At the time of installation
18.1.10 Requirements		

19.1	Areas to Assess	Yes	No	Assessor Comments
19.1.1	Fire Doors are provided where necessary, are identified and freely available for use	√		All communal fire doors were inspected, No internal inspection of the flat entrance doors was undertaken due to carrying out inspection during COVID 19.
19.1.2	Corridor smoke-control doors are provided where necessary	✓		All communal fire doors were inspected.
19.1.3	Fire and smoke–control doors are in good condition, tight fitting to and free from distortion	✓		All communal fire doors were inspected.
19.1.4	Smoke stop and intumescent seals are present, and in good condition	√		
19.1.5	Self-closing devices are present and functional and engage with the latch	✓		The communal door closers were functioning correctly.
19.1.6	Where double doors are present, they close in line and have a selector where necessary			
19.1.7	The door threshold gap is consistent and doesn't foul the floor covering	√		

19.1	Areas to Assess	Yes	No	Assessor Comments
19.1.8	Doorframes are secure to the wall with no visible gaps present.	√		
19.1.9	Fire and smoke-control doors are indicated by signs	*		
19.1.10	Glazing panels are fire rated, undamaged with fire rated framework	*		All glazing panels were as built, all were visually inspected during the assessment.
19.1.11	Automatic self-closing devices/hold open devices are present		✓	
19.1.12	Automatic self-closing devices/hold open devices are closed at critical times			
19.1.13	Automatic self closers are interlinked to the fire alarm system via smoke detection and/or alarm sounder circuit			
19.1.14	Correct signage is present for automatically self- closing doors			

20.1	Areas to Assess	Yes	No	Assessor Comments
20.1.1	Enough internal escape routes are provided, available, appropriate for the likely users and lead to a place of safety	√		
20.1.2	Travel distances are acceptable	✓		
20.1.3	Internal Escape Routes are adequately indicated by appropriate pictogram signs along their entire route to final exit point	√		
20.1.4	Signs are in good condition, unobstructed, legible and firmly fixed	✓		
20.1.5	Sliding or revolving doors are present on escape routes		√	
20.1.6	Pass doors are provided for sliding or revolving doors			
20.1.7	Doors open in the direction of escape where appropriate	✓		
20.1.8	Final exit doors are visible, accessible and easily opened	\		
20.1.9	Means of escape doors not in normal use are routinely checked	~		Generally inspected during routine maintenance.
20.1.10	Final exit doors are indicated internally by appropriate pictogram signs	✓		
20.1.11	All Final Exit Points are indicated externally 'Fire Exit – Keep Clear'	√		

20.1	Areas to Assess	Yes	No	Assessor Comments
20.1.12	Final exit points lead into areas from where further dispersal can take place and are not in danger from fire and smoke	√		
20.1.13	Where required and appropriate, panic fastenings are fitted to the final exit doors			
20.1.14	All panic fastening methods of use are indicated e.g. 'Push Bar/Pad to Open'			
20.1.15	Non-standard securing devices are present on final exit doors with their method of operation clearly displayed	√		St Annes Ct has electro magnetic door securing devices installed that do not disengage in the event of a fire alarm activation
20.1.16	Where non-standard securing devices are fitted, they are appropriate for the likely users	✓		
20.1.17	Where fitted, magnetic locks release automatically on fire alarm actuation and/or have manual override		√	The final exit doors are not interconnected Fireman's switch will override the door entry system.
20.1.18	Where present, exit doors or corridor doors with powered, automatic opening revert to normal operation during fire alarm actuation	✓		
20.1.19	Internal corridor escape routes are protected where necessary	✓		
20.1.20	Inner rooms are protected by auto detection or vision panels	✓		
20.1.21	Protected stairwell escape routes are provided	✓		
20.1.22	Floors, walkways, floor coverings, stairs and stair coverings are in good condition, free from obstruction or trip hazard	\		
20.1.23	Handrails are provided on stairs and are in good condition	√		
20.1.24	Internal escape routes are adequately lit by artificial or natural lighting	✓		
20.1.25	Emergency Escape Lighting is provided along internal escape routes	✓		

20.1	Areas to Assess	Yes	No	Assessor Comments
20.1.26	The internal Emergency Escape Lighting is in good repair	✓		
20.1.27	Emergency Escape Lighting is regularly tested in accordance with BS5266, findings and corrective works recorded		√	Action raised

21.1	Areas to Assess	Yes	No	Assessor Comments
21.1.1	External escape routes are provided, available, free from obstruction or hazard and lead to a place of safety	√		
21.1.2	External escape routes are regularly monitored and maintained to ensure continuing availability for use	✓		
21.1.3	External escape routes are clearly indicated by pictogram signs along their entire route to final exit point			
21.1.4	Glazing within 2 metres horizontally and 9m vertically below an external escape stair, is fire resisting			
21.1.5	External metal escape stairs and platforms have been examined by a structural engineer within the last three years			
21.1.6	Records of examination of stairs are maintained and available			
21.1.7	Stair treads and handrails are in good condition			
21.1.8	External escape routes are adequately lit by mains powered lighting			
21.1.9	Where not, the control switch is clearly identifiable			
21.1.10	Emergency Escape Lighting is provided along external escape routes			
21.1.11	External Emergency Escape Lighting is in good repair			

21.1.12 External Emergency Escape Lighting is regularly		
tested and findings recorded		

22.1	Areas to Assess	Yes	No	Assessor Comments
22.1.1	Portable Firefighting Equipment is provided, sufficient in number and appropriate to the risks present	V		
22.1.2	Dry Powder extinguishers are present		✓	
22.1.3	It is wall mounted or on dedicated floor stands with the operating handle at approximately 1m from the ground	√		
22.1.4	Extinguisher security tags are present	✓		
22.1.5	Portable Firefighting Equipment positions are clearly indicated by signs where necessary and accessible on exit routes	√		
22.1.6	Portable Firefighting Equipment is annually tested to BS5306 -3 2009 and results recorded	✓		Lift motor room and bin stores only
22.1.7	Access for Fire and Rescue is satisfactory		✓	No parking in "Emergency Services Only" safety zone markings would improve this
22.1.8	A fire hydrant is in close proximity to the building	√		
22.1.9	It is clearly marked and freely available		→	
22.1.10	An open water supply is provided		✓	
22.1.11	Where provided, the Fire and Rescue Service access is maintained	√		

23.1	Areas to Assess	Yes	No	Assessor Comments
23.1.1	Sprinklers or drenchers are present	√		
23.1.2	They cover the whole property			
23.1.3	Spare heads are available			
23.1.4	The system is maintained with servicing records available which are appropriate and current			
23.1.5	Fixed flooding Installations are present			
23.1.6	The system is maintained with servicing records available which are appropriate and current			
23.1.7	A Dry Riser installation is present	✓		
23.1.8	The inlet and outlets are clearly indicated and available for use	√		
23.1.9	The system is maintained in accordance with BS9990 2006, servicing records are available, appropriate and current		✓	Action raised

2	24.1	Areas to Assess	Yes	No	Assessor Comments
		There is smoke/ventilation control present	✓		
2	24.1.1				
		The system is maintained, servicing records are	✓		Action raised
2	24.1.2	available, appropriate and current			
		Ventilation ducts which breach compartments			
2	24.1.3	have automatic fire dampers			
		The dampers are identifiable, maintained with			
2	24.1.4	servicing records available which are appropriate and current			

25 Fire evacuation lift and fire fighting shafts

25.1	Areas to Assess	Yes	No	Assessor Comments
	A firefighting/evacuation lift is provided		✓	
25.1.1				
	It is clearly indicated as a			
25.1.2	firefighting/evacuation lift			
	DO NOT USE IN THE EVENT OF FIRE	✓		
25.1.3	signage is displayed			
	The lift is maintained with servicing records	✓		
25.1.4	available which are appropriate and current			
	A firefighting shaft is provided		✓	
25.1.5				

	The firefighting shaft is protected and		
25.1.6	maintained in good order		

26.1	Areas to Assess	Yes	No	Assessor Comments
26.1.1	A manually operated, electrical Fire Warning System is provided throughout the property	√		Only within the plant room
26.1.2	The alarm sound is uniform, clearly identifiable and audible throughout the property	√		
26.1.3	Call points are sited appropriately, available and readily identifiable	✓		
26.1.4	The warning system contains sensory warning devices including visual and aural stimuli	✓		
26.1.5	Automatic Detection is provided throughout the property	✓		
26.1.6	The automatic detection type is appropriate for the identified risks	√		
26.1.7	The Fire Warning system is connected to an Alarm Receiving Centre (ARC)			All activations are dialled through to BAYDALE.
26.1.8	The Testing regime is in accordance with BS5839 and results recorded	√		Migration to a digital solution is currently being considered by whg to address this issue.
26.1.9	Automatic detection is tested in accordance with BS5839 and results recorded		✓	Action raised
26.1.10	A zone plan is available at the Control Panel	√		The plan consists of a detailed list of zones not a plan layout

27.1	Areas to Assess	Yes	No	Assessor Comments
27.1.1	There is a Fire Safety Management Policy	✓		
27.1.2	The Responsible Person is identified	✓		
27.1.3	They meet regularly and communication is effective		→	
27.1.4	There has been a recent Fire and Rescue Service inspection	✓		
27.1.5	Improvement notices have been served		✓	
27.1.6	Improvement Notices/inspection results have been actioned and completed			
27.1.7	There are previous Fire Risk Assessments	✓		
27.1.8	Previous assessment findings have been actioned and completed	✓		Undertaken annually
27.1.9	Risks to Occupants identified in the FRA have been notified to them			Whg intend to publish the findings of this risk assessment to all customers following it's completion

28.1	Areas to Assess	Yes	No	Assessor Comments
28.1.1	Fire Safety is included in Induction training for all new staff	✓		
28.1.2	Staff members are regularly trained in Fire Safety topics appropriate to their responsibilities			
28.1.3	Fire Marshalls / Wardens / Co-ordinators are trained and appointed			
28.1.4	Training is delivered by competent persons			
28.1.5	Training includes the practical use of Firefighting equipment			
28.1.6	Where PEEPs are in use, Fire Marshalls / Wardens are aware of them			
28.1.7	Evidence of training is maintained			
28.1.8	Employees/occupants are informed of Fire Risk Assessment findings			
28.1.9	Visitors and / or Contractors are given a Fire Safety brief or copy of procedures			
28.1.10	The impact of outside undertakings on fire safety is assessed and Occupants informed of any corrective measures			

29.1	Areas to Assess	Yes	No	Assessor Comments			
29.1.1	Emergency Evacuation Procedures are identifiable in common areas and/or alongside at each call point	V		Fire Action Plan notices are displayed on each floor.			
29.1.2	Emergency Evacuation Procedure Notices include a floor plan layout						
29.1.3	The procedures identify how the Fire and Rescue Service is to be summoned			The profile of the customers within St Annes Ct is mixed there may be residents that will have mobility and sensory impairments. St Annes Ct is a residential building and not staffed, therefore customers must ensure they take necessary fire precautions within their flat and regularly familiarise themselves with whg's stay safe policy and fire safety guidance.			
29.1.4	The Evacuation Procedures consider disability with reference to the evacuation chairs / lifts / refuges		√				
29.1.5	Evacuation Drills are carried out frequently and results recorded			See 29.1.4			
29.1.6	All employees / occupiers participate			See 29.1.4			
29.1.7	Assembly Point locations are clearly identified and are suitable and adequate for access, safety in use and numbers			See 29.1.4			
29.1.8	Evacuation Chairs are available and/or located on all levels			See 29.1.4			
29.1.9	Sufficient trained users are available and practice use of the chair			See 29.1.4			
29.1.10	Refuge Areas are provided and clearly identified including dedicated route			See 29.1.4			

29.1.11	Refuge areas have communications which are routinely tested		See 29.1.4
29.1.12	A suitable lift is identified and available for use during evacuation		See 29.1.4
29.1.13	The Emergency procedures / signs make reference to the use of evacuation chairs / lifts / refuges		See 29.1.4

30.1	Areas to Assess	Yes	No	Assessor Comments
30.1.1	There is a detailed Emergency Plan available and known to Occupiers			WMFS to co ordinate when applicable
30.1.2	A Firefighting Plan containing property specific information is provided and immediately accessible			WMFS to co ordinate when applicable
30.1.3	The Firefighting Plan is regularly reviewed and contains current information including floorplans			WMFS to co ordinate when applicable
30.1.4	The property location is easily recognised externally by the Fire and Rescue Service	✓		
30.1.5	Persons are nominated and trained to respond to fire			The profile of the customers within St Annes Ct is mixed there may be residents that will have mobility and sensory impairments. St Annes Ct is a residential building and not staffed, therefore customers must ensure they take necessary fire precautions within their flat and regularly familiarise themselves with whg's stay safe policy and fire safety guidance.
30.1.6	A Person is nominated to liaise with the Fire and Rescue Service		✓	









